



Surface Soil Remediation Results  
as of 5 October 2016  
Sediment Processing Facility




## Surface Soil Sample Location SS-301

Sumac shrubbery is at the top of slope to the Lock 8 Diversion Canal.  
Subsurface utilities not marked on figure.




**Surface Soil Sample Location SS-306**



▲ 0-2" Sample at perimeter of proposed excavation


**Surface Soil Sample Location SS-306**





## Surface Soil Sample Location SS-329

Subsurface utilities not marked on figure.



## Surface Soil Sample Location SS-329

Subsurface utilities not marked on figure.